
Morse Watch / Timer kit

Jackson Harbor Press 1418 Foss Rd. Washington Island, WI 54246 http://wb9kzy.com wb9kzy@wb9kzy.com

Schematic



Circuit Board Top View Parts Placement Diagram Grounded mounting hole Piezo mour Output Ground 4-40 C5 C4 +Vin D U2, Ground 0 latching U1 Ground I relay Rľ Switch Common ⊐normally open normally closed Grounded UP Ground mounting hole 4-40 Circuit Board Bottom View