



PICPADL kit

Jackson Harbor Press
<http://wb9kzy.com>
wb9kzy@wb9kzy.com


Top view bare board




Bottom view bare board




PICPADL Kit Schematic



board photos Top view



Bottom view



Don't let this happen to you:

Overenthusiastic tightening on the bolt holding the L bracket etched off the insulating solder mask resulting in pin 4 being shorted to ground.
Electrical tape can be applied to prevent the short.

